

HOW TO RUN A LATHE

PRICE 50 CENTS



SOUTH BEND LATHE WORKS

South Bend, Ind., U. S. A.



South Bend Lathes are built in the following 39 Sizes

No. AND SWING OF LATHE	LENGTH OF BED					
	4 Ft.	5 Ft.	6 Ft.	7 Ft.	8 Ft.	10 Ft.
No. 26-1'	11'x4'	11'x5'	11'x6'			
No. 29-11'	11'x4'	11'x5'	11'x6'			
No. 30-12'		12'x5'	12'x6'	12'x7'	12'x8'	
No. 32-13'		13'x5'	13'x6'	13'x7'	13'x8'	13'x10'
No. 34-13'		13'x5'	13'x6'	13'x7'	13'x8'	13'x10'
No. 35-13'		13'x5'	13'x6'	13'x7'	13'x8'	13'x10'
No. 37-15'		15'x6'	15'x7'	15'x8'	15'x10'	
No. 40-16'		16'x6'	16'x7'	16'x8'	16'x10'	16'x12'
No. 44-18'		18'x6'	18'x7'	18'x8'	18'x10'	18'x12'

"HOW TO RUN A LATHE"

By a Practical Machinist and Mechanical Engineer

This little book calls attention to some of the practical and necessary details that the beginner should be familiar with in operating a screw cutting engine lathe.

It has been said, that if a man of mechanical turn of mind learns how to run a lathe and will observe the three fundamental rules of the shop, he can become a first-class mechanic. Following are the rules:

Keep your lathe clean and well oiled.

Keep your tools sharp.

Take your measurements accurately.

A copy of this little book, "How to Run a Lathe," is included free, and will be found packed in the box with the regular equipment of each South Bend Lathe.

"How to Run a Lathe" would make an excellent gift to a friend who is interested in mechanics. We will mail a copy postpaid direct to his address upon receipt of price. **Stamps accepted.**

How to Run a Lathe

How to erect, care for and operate a
Screw Cutting Engine Lathe

REVISED EDITION

No. 3

Copyright 1914, by

O'BRIEN BROTHERS
J. J. O'Brien—M. W. O'Brien


SOUTH BEND LATHE WORKS

South Bend, Indiana, U. S. A.

425-425-427 E. Madison St.

Manufacturers of

SOUTH BEND LATHES



SOUTH BEND, INDIANA, U. S. A.

2


PRACTICAL LAYOUT FOR A SMALL MACHINE SHOP

The drawing on the opposite page illustrates a practical layout for a small machine shop. The line shaft is attached to the joists parallel to the side wall, and leveled perfectly so that the shaft will run free and easy. A line shaft $1\frac{1}{2}$ inch in diameter, having a speed of 200 revolutions per minute, is recommended for the small shop.

An electric motor is mounted on a bracket attached to either side wall, high enough so that the belt will not interfere with the workmen passing underneath. If a gas engine is used instead of an electric motor, the engine may be located conveniently in the corner, as shown.

Countershaft for lathe is attached to the joists about 6 ft. distant from the line shaft. The countershaft should be leveled carefully, the axis being parallel to that of the line shaft. The countershaft belt at head end of lathe is straight; the reverse belt is crossed. Arrows show the direction in which the belts run. The two pulleys on line shaft for driving countershaft are of the same diameter. Some prefer the pulley driving the reverse belt to be 1 inch larger in diameter, so that for thread cutting the carriage may be reversed at high speed. Wood split pulleys crown face are recommended for the line shaft.

A three-horse power motor has ample power to drive the equipment shown in drawing, assuming that the lathe is not larger than 16 inch.



Cut of Lathe showing principal parts numbered

ORDERING REPAIR PARTS

In ordering repair parts for lathe, order by number of part and give size of lathe that the part is to be used on, because the part numbers apply to all size South Bend lathes from 11 to 18 inch swing inclusive.

NUMBER AND NAME OF LATHE PARTS ON DRAWING

No.	No.
1 Bed.	55 Tail Stock Wrench.
2 Power Legs.	56 Tail Stock Clamp Plate.
3 Lead Screw Bracket F.	59 Saddle.
4 Lead Screw Bracket R.	61 Saddle Gb.
10 Head Stock.	62 Saddle Lock.
11 Head Stock Cap, Large.	63 Cross Feed Bushing.
12 Head Stock Cap, Small.	64 Cross Feed Gra. Collar.
13 Head Stock Clamp Plate.	65 Cross Feed Nut.
14 Spindle Cone.	66 Plain Rest.
15 Bull Gear.	67 Thread Cutting Stop.
16 Bull Gear Clamp.	70 Apron.
17 Cone Pinion.	71 Apron Hand Wheel.
18 Quill Gear.	72 Lead Screw Half Nut.
19 Quill Sleeve.	73 Lead Screw Half Nut Gb (2).
20 Quill Sleeve Pinion.	74 Nut Cam.
21 Rec. Shaft Misting.	75 Nut Cam Washer.
22 Bronze Box, Large.	76 Rack Pinion Gear.
23 Bronze Box, Small.	77 Auto. Apron Worm Wheel.
24 Rack Gear Lever.	78 Auto. Apron Clutch Sleeve Bushing.
25 Spindle Take up Nut.	79 Auto. Apron Worm Bracket.
26 Reverse Bracket.	80 Auto. Apron Clutch Sleeve.
27 Reverse Twin Gears (2).	81 Auto. Apron Clutch.
28 Reverse Gear.	82 Auto. Apron C. P. Star Knob.
29 Stud Gear.	83 Auto. Apron C. P. Lever.
30 Spindle Reverse Gear.	84 Auto. Apron C. P. Gear.
31 Change Gear Bracket.	85 Auto. Apron C. P. Gear.
32 Change Gears and Turning Gear.	86 Auto. Apron Idler Gear.
33 Change Gear Idler.	87 Auto. Apron Idler Gear Pinion.
34 Change Gear Idler Bushing.	89 Compound Rest Top.
35 Change Gear Collar on L. G.	91 Compound Rest Swivel.
36 Idler Gear 5 to 1 Large.	92 Compound Rest Bottom.
37 Idler Gear 2 to 1 Small.	93 Compound Rest End Cap.
38 Idler Gear Bushing 2 to 1.	94 Compound Rest Bushing.
39 Thrust Collar on Lead Screw.	95 Compound Rest Nut.
40 Large Face Plate.	96 Compound Rest Chip Guard.
41 Small Face Plate.	
50 Tail Stock Top.	
51 Tail Stock Base.	
52 Tail Stock Nut.	
53 Tail Stock Hand Wheel.	
54 Tail Stock Binding Lever.	

Countershaft

100 C. S. Friction Pulleys (2).
101 C. S. Friction Spiders (2).
102 C. S. Friction Fingers (2).


No.	No.
102 C. S. Cone.	212 Apron Hand Wheel Pinion.
104 C. S. Collars (4).	214 Tail Stock Screw.
105 C. S. Yoke Lever.	217 Reverse Shaft.
106 C. S. Boxes (2).	224 Apron Rack Pinion Stud.
107 C. S. Hangers (2).	222 Reverse Shoulder Screws (2).
108 C. S. Shipper Nut.	220 Compound Rest Screw.
109 C. S. Yoke Cone.	221 Auto Cross Feed Stud.
200 Head Stock Spindle.	212 Apron Half Nut Stud (2).
201 Tail Stock Spindle.	213 Tool Post Screw.
202 Back Gear Eccentric Shaft.	234 Apron Idler Gear Stud.
203 Apron Worm.	235 Cam Cap Screw.
204 Apron Rack Pinion.	228 Apron Worm Washer.
205 Spindle Sleeve.	229 Comp. Rest Steel Wedge.
207 Spindle Thrust Collar.	240 Gap Bridge Pins (2).
208 Apron Worm Collar.	241 Reverse Stud Gear Washer.
209 Tool Post Block.	242 Change Gear Spindle Knob.
210 Carriage Lock Collar Screw.	250 Tool Post.
211 Compound Rest Swivel Bolt.	251 Tool Post Ring.
212 C. G. Bracket Collar Screw.	252 Tool Post Wedge.
213 Reverse Collar Screw.	253 Tool Post Wrench.
214 Bull Gear Clamp Collar Screw.	254 Compound Rest Wrench.
215 Apron Worm Clutch Sleeve Hexagon Nut.	260 Centers (2).
216 Compound Rest Swivel Stud.	261 C. S. Shaft.
217 Steady Rest Lock Bolt.	262 C. S. Shipper Rod.
218 Auto Cross Feed Lever Stud.	263 C. S. Expansion Wedges.
219 Reverse Steel Collar.	271 Rack.
220 Apron Clutch Sleeve Pinion.	276 Cross Feed Ball Crank.
221 Compound Rest Gibs (2).	277 Compound Rest Handle.
222 Plain Rest Gibs.	278 Tail Stock Set Over Screws (2).
223 Auto Apron Clutch Screw.	279 Tail Stock Clamping Bolt, Nut and Washer.
224 Cross Feed Screw.	280 Lead Screw.

HORSE POWER

The horse power required to drive a South Bend lathe to its full capacity under a maximum load is as follows:

11-inch lathe	1/2 horse power
12-inch "	3/4 "
13-inch "	1 "
15-inch "	1 1/2 "
16-inch "	2 "
18-inch "	2 1/2 "

We have seen a 13-inch lathe driven by a half horse motor and the power seemed amply sufficient for a medium load.




INSIDE VIEW OF AUTOMATIC APRON

Drawing shows detail of the inside view of the automatic apron on South Bend Lathes. Note that the lead screw is splined for driving worm which operates both the power cross feed and the automatic longitudinal feed. This arrangement allows the thread of the lead screw to be used for screw cutting only, because in screw cutting we use only the half nuts No. 72. This is the reason a splined lead screw on a lathe should last a lifetime.

Another important feature in this automatic apron is that the cross feed and the longitudinal feed can be operated **only one at a time**, so it is impossible when one feed is in operation for the other feed to drop in. This feature will be appreciated by the operator.

No.	No.
70 Apron.	85 Auto Apron C. F. Gear.
71 Apron Hand Wheel.	86 Auto Apron Idler Gear.
72 Lead Screw Half Nut.	87 Auto Apron Idler Gear Pinion.
73 Lead Screw Half Nut Gibs (2).	205 Auto Apron Worm.
74 Nut Cam.	204 Auto Apron Rack Pinion.
76 Rack Pinion Gear.	206 Auto Apron Worm Collar.
77 Auto Apron Worm Wheel.	218 Auto Apron C. F. Lever Stud.
79 Auto Apron Worm Bracket.	223 Auto Apron Clutch Screw.
80 Auto Apron Clutch Sleeve.	225 Auto Apron Hand Wheel Pinion.
81 Auto Apron Clutch.	224 Auto Apron Rack Pinion Stud.
82 Auto Apron C. F. Star Knob.	221 Auto Apron Cross Feed Stud.
83 Auto Apron C. F. Lever.	200 Lead Screw.
84 Auto Apron C. F. Lever Knob.	



IMPROVED REVERSE

The above drawing shows detail of the Improved Reverse placed on the head of the South Bend Lathe within easy reach of the operator at all times. The Reverse changes the direction of the lead screw. For example, cutting threads right or left, driving the automatic feed right or left, and operating the cross feed in or out.


The Reverse can be shifted instantly without changing gear, or it may be left in a neutral position when spindle is to be run at high speed for such work as filing, polishing, etc.

No.

- 1 Bed.
- 12 Head Stock Cap, Small.
- 14 Spindle Cone.
- 16 Quill Gear.
- 20 Quill Sleeve Pinion.
- 21 Ecc. Shaft Bushing.
- 24 Reverse Bracket.
- 27 Reverse Twin Gears. (2)
- 28 Reverse Gear.
- 29 Stud Gear.
- 30 Spindle Reverse Gear.
- 31 Change Gear Bracket.

No.

- 32 Change Gears.
- 36 Idler Gear 2 to 1 large.
- 37 Idler Gear 2 to 1 small.
- 42 Idler Gear Bolt.
- 298 Head Stock Spindle.
- 299 Eccentric Shaft.
- 212 C. G. Bracket Collar Screw.
- 213 Reverse Collar Screw.
- 227 Reverse Shaft.
- 228 Reverse Shoulder Screws (2).
- 300 Lead Screw.



GRADUATED COMPOUND REST

The above drawings show side elevation and end view from the rear of a practical Compound Rest. The Compound Rest Top swivels in a complete circle fastened by two T bolts. It is graduated in degrees so that various angles may be obtained.

Compound Rest Base is fitted with a chip guard No. 96, which prevents chips falling on the cross feed screw.


Compound rest is always recommended on a Lathe used for general all-around work in the Machine Shop.

No.

- 90 Compound Rest Top.
- 91 Compound Rest Swivel.
- 92 Compound Rest Bottom.
- 94 Compound Rest Bushing.
- 96 Compound Rest Chip Guard.
- 211 Compound Rest Swivel Bolts (2).

No.

- 221 Compound Rest Bottom Gib.
- 230 Compound Rest Screw.
- 237 Compound Rest Top Gib.
- 258 Compound Rest Cone Point Gib.
- 277 Compound Rest Handle.



16-INCH LATHE AND REGULAR EQUIPMENT

The regular equipment illustrated under Lathe is included in the price and consists of—

- Large Face Plate
- Small Face Plate
- 2 Steel Centers
- Center Rest
- Follower Rest
- Change Gears
- Adjustable stop for Screw Cutting
- Necessary Wrenches
- Double Friction Countershaft

All securely crated and packed f. o. b. cars, Factory.

THE NEW LATHE


On the arrival of the new lathe remove crating and unpack the parts found in box. See that nothing is overlooked in the wrappings or excelsior. The regular equipment that is included in the price of lathe is illustrated and described on the opposite page. Check up the various parts with this list.

The bright parts of the lathe are covered with grease in order to prevent rusting. Remove this grease with a rag that has been dipped in coal oil or kerosene, then wipe dry. Clean all gears thoroughly, including back gears and change gears. Clean each tooth separately, because sawdust and dirt may have lodged there while the lathe was in transit.

Select the most desirable location in your shop for the lathe. There are several conditions that will govern this spot, such as the position of line shaft, direction of the light, etc. The best results are obtained when the operator working at the lathe has the light coming from a point over his right shoulder.

Study drawings and descriptions of "Practical Layout For Small Shop" on pages 2 and 3.

The floor on which the lathe rests should be solid so that the lathe stands on a firm foundation. If there is any shake the floor should be braced from underneath. There should be a space free all around the lathe as the operator may have an occasional job where it will be necessary that he work from all sides of the machine.



SIZE OF LATHE

The size of an Engine Lathe is determined by the **swing** and **length of bed**. See above drawing.

R represents the radius, one-half the swing.

A represents the swing.


B represents the distance between centers.

C represents the length of bed.

The drawing on opposite page shows the front erection view of lathe and countershaft. The height of the countershaft should be at least 5 feet from spindle in order to give proper belt distance. Seven feet high would give better results.

The countershaft may be set on either side of the line shaft, being governed by the position of the lathe. See pages 2 and 3. The hangers of countershaft must be set in position so that the extension on hanger through which the shipper rod passes will point toward the line shaft, in order that the shipper rod may guide the belts.

When the location of the lathe is settled, attach the countershaft to the ceiling. A good plan for attaching is to arrange as per drawing herewith. Assemble the countershaft complete, bolt the hangers to the 2 x 6's, in order to get the proper distance between hangers. Now remove the countershaft from the hangers, and fasten the 2 x 6's (with hangers) to the ceiling. Secure with several lag screws. Then place the countershaft back in the hangers, level it up properly, adjusting so that the axis of the countershaft is parallel to that of the line shaft.



Plan of Attaching Countershaft to Joists

SETTING THE LATHE IN POSITION

Countershaft fastened in position, adjust the lathe so that the belt will track between spindle cone and countershaft cone. It is necessary that the axis of the lathe spindle is parallel to that of the countershaft. It is not necessary that the lathe spindle be directly underneath the countershaft, (looking at the lathe from the end) as the lathe may be from 6 to 12" either one side or the other of a vertical line dropped from countershaft. See drawing page. 2.

LEVELING LATHE

The accuracy of a lathe depends a great deal upon the manner in which it is erected and leveled. Place level across the ways near the head stock. Repeat this operation at several points the entire length of the bed leveling carefully in every direction. Shim underneath the legs with shingles until the lathe is perfectly level, then, when countershaft and spindle cones are in their relative position so that belts will track properly, fasten lathe firmly to the floor using lag bolts.

BELTING

Leather belt is always recommended. In belting line shaft to countershaft two belts are used. The belt nearest the head end of lathe is usually straight, the other is the reverse or cross belt. See drawing page 2. The countershaft belts should be so arranged that when the shipper rod is thrown over in the direction of the lathe head the spindle of the lathe should revolve so that the top spindle cone runs toward the operator when he is in front of the lathe.

RULES FOR CALCULATING THE SPEED AND SIZE OF PULLEYS

The driving wheel is called the driver, and the driven wheel the driven or follower.

The R. P. M. is the number of revolutions per minute.

Problem 1.

The revolutions of driver and driven, and the diameter of the driven, being given, required the diameter of the driver.

RULE.—Multiply the diameter of the driven by its number of revolutions, and divide by the number of revolutions of the driver.

Problem 2.

The diameter and revolutions of the driver being given, required the diameter of the driven to make a given number of revolutions in the same time.

RULE.—Multiply the diameter of the driver by its number of revolutions, and divide the product by the required number of revolutions.

Problem 3.

The diameter and number of revolutions of the driver, with the diameter of the driven, being given, required the revolutions of the driven.

RULE.—Multiply the diameter of the driver by its number of revolutions, and divide by the diameter of the driven.

Problem 4.

The diameter of driver and driven, and the number of revolutions of the driven, being given, required the number of revolutions of the driver.

RULE.—Multiply the diameter of the driven by its number of revolutions, and divide by the diameter of the driver.

SPEED OF LATHE COUNTERSHAFT

Size of Lathe	Size of Friction Pulley	Speed of Countershaft
11 in.	7 x 2 in.	250 R. P. M.
12, 13 in.	8 x 2 1/4 in.	225 R. P. M.
15 in.	10 x 3 in.	200 R. P. M.
14, 16 in.	10 x 4 in.	180 R. P. M.

OILING LATHE

Frequent oiling is necessary for a lathe or any other machine. A good grade of machine oil gives best results. After lathe is located and fastened to the floor and countershaft attached to the ceiling the next step is oiling the revolving parts of the lathe. Every oil hole should be located and a generous supply of machine oil used flushing each revolving part, not only to give it the necessary oil, but also to make sure that any dust or dirt that may have located in the bearings be washed out.

In oiling the head stock spindle, the mechanism in the apron and the lead screw bearings, all should receive special attention, so that the parts will run free and easy. The same attention should be given to the countershaft before it is attached to the ceiling and after it is set in position.

Oil the spindle cone bearings by removing two small headless set screws which will be found on the large and small steps of the cone. Give each a generous supply of oil, then replace the screws as they prevent dirt reaching the spindle.

Oil the back gear quill through two small oil holes for that purpose. Be sure to use plenty of oil on the lead screw and half nuts before cutting a thread.

Oil the head spindle bearings frequently. It is a very good plan to go over the lathe at least once a day to see that every revolving part has received sufficient oil.

STARTING LATHE

Lathe is now ready to start. See that the shipper rod is properly adjusted. Arrange spindle cone for open belt by throwing out the back gear lever which releases the back gears, then fasten bull gear clamp to spindle cone. Now the lathe is arranged for open belt. If the spindle runs freely on open belt stop lathe, loosen bull gear clamp, slip clamp down as far as it will go, then fasten. Now throw in back gear lever connecting back gears. Lathe is now running back geared.

Never throw in back gears while lathe spindle is running.

Never throw out back gears while lathe spindle is running.

Next, connect reverse gear with spindle gear. Fasten the collar on reverse lever, locking lever in position.

Never throw in reverse gear while lathe is running.

Never throw out reverse gear while lathe is running.

Connect gears on change gear bracket with gear on spindle reverse stud.

In this connection there should be a slight play or shake between the teeth of the two connecting gears. **This point is important.** In connecting any two gears there should always be a little clearance between the top of the teeth of one gear and the bottom of the teeth of the opposite. When two or more gears are in mesh in this manner they will operate with very little friction and give best results.

When the change gears are connected to the reverse spindle gear lock the change gear bracket in position by fastening the collar screw in front, then start lathe, all gears being in mesh.

Never connect, or disconnect, change gear bracket gears with reverse spindle gears when lathe is running.

CARRIAGE

The saddle and apron combined is called the carriage of the lathe. Oil the ways and V's of the lathe bed thoroughly, running the carriage back and forth over the oiled surface, so that the oil is distributed properly. Oil the rear saddle gib by placing some oil on your finger and spreading this oil under the rear way of the lathe where the saddle gib slides.

FACE PLATE

Before mounting a face plate on the nose of spindle all dirt should be removed from the thread of spindle and also from the threaded hole in the face plate. A few drops of oil on the spindle nose will allow the plate to screw on much easier. If the face plate screws on tightly there must be dirt in the threads. Unscrew the plate, remove the dirt, try again. The back of the face plate should go tight up against the shoulder of spindle. The same attention should be given in attaching a lathe chuck to spindle nose.

LATHE CENTERS

Lathe centers are made of tool steel. The head center is always soft because it revolves with the work, and should be trued up occasionally, especially when one is to do an accurate job between centers. For truing a center, remove the face plate, use a flat-nosed tool in tool post and take a light chip off the center, being sure to keep the angle 60 degrees as shown in cut herewith.



Testing angle of center, by center gauge

The tail spindle center is always hardened, because when a shaft is being machined on centers it revolves on the tail center so that there is considerable wear. The tail center should be trued up occasionally. In each case it should be annealed, placed in the head spindle and machined true, and hardened.

The shank of a lathe center conforms to a standard taper, usually Morse standard. Each time the center is placed in spindle care should be taken to see that both spindle hole and center is free from dirt.

Never put your finger in the spindle hole to remove dirt while the lathe is running. Always use a stick with a piece of rag attached.

Always remove center from head spindle when using a lathe chuck on the spindle.



Special Drilling Chuck



Screw Center



Drill Pad



Spur Center



Crotch Center



Cup Center

LATHE ACCESSORIES

The above cuts show a number of accessories that are very useful for various classes of lathe work.

The special drilling chuck screws on to the spindle nose of the lathe. The centers, drill pad, etc., are machined taper, so that they fit both head and tail spindles of the various size lathes.

With these accessories one is enabled to do a great deal of general work in a lathe, such as drilling of every description on metal, also wood turning and pattern making, etc.

CENTERING

To turn or machine a shaft on centers in the lathe it is necessary that the shaft be centered.

There are many way of centering. The simplest is to chalk the end of the shaft to be centered. Scratch two lines at right angles to each other, and where these lines intersect will be the approximate center of the shaft. See Fig. 4.





Fig. 4

Drive center punch on the intersection of lines on both ends of the shaft. Place the shaft thus punched on the centers of the lathe, revolve by hand; if it does not run true, hold a piece of chalk to the shaft while revolving and it will mark the high spots. Place shaft in the vise once more, drive the center in the direction necessary to have the shaft run true.

Drill and countersink each end of the shaft until a depth is reached sufficient to support the shaft on the centers while it is being turned. A good method of countersinking is shown in Fig. 5.

Long shafts may be centered with a breast drill or brace and bit. The regular countersinks may be used in the same manner.




COUNTERSINKING A SHAFT

A drill chuck is fitted to the head spindle of lathe holding a combined drill and countersink. (see Fig. 5-B). The shaft has already been center punched. Place one end of shaft on tail center and feed by turning the wheel of tail stock. Allow the countersink to enter the proper depth, countersink the other end in the same manner. The shaft is now ready to be machined.


DRILL AND COUNTERSINK

The depth of the countersink depends upon the diameter of the shaft to be machined, and somewhat upon the depth of the cut to be taken. It is important that the countersink have the same taper as the lathe center, 60 degrees.



IMPROPER CENTERING

Fig. 6 shows a shaft countersunk in such a way that it does not fit on the lathe center, but rests on the point only. This very soon destroys the lathe center and will also ruin the shaft.



PROPER COUNTERSINK

Fig. 7 shows the style of countersink which gives best results. A small hole is first drilled beyond the depths of the point of the lathe center; it is then countersunk on an angle of 60 degrees to fit the lathe center.

DRILL AND COUNTERSINK COMBINED

Fig. 5B is a combined drill and countersink, which is both the center drill and countersink. Centering may also be done by a small twist drill for the center hole and a larger twist drill ground 60 degrees following as a countersink.



Fig. 5B




Fig. 8



Fig. 9

Figs. 8 and 9 show two style countersinks that are used to follow the small center drill for countersinking.



TURNING A STEEL SHAFT

The illustration above shows a steel shaft being machined on a lathe between centers. The shaft is driven by a common lathe dog, the tail of which enters the slot in the face plate. It will be noted that a heavy chip is taken, which requires considerable power, so the lathe is running with back gears in mesh.

The lathe is a universal machine for the shop. With various attachments it may be equipped to do the work of a drill press and to some extent of a milling machine, a shaper and a planer.

In addition to the common lathe dog, a clamp lathe dog is used for holding rectangular pieces that are being driven in the lathe. (See illustration). Sometimes a shaft is driven by holding one end in the lathe chuck, the other end being supported by a steady rest. See Fig. 18, page 38.

Common Lathe Dog




Clamp Lathe Dog



FACING END OF SHAFT

When a shaft is being machined on centers, if accurate work is to be done, the end of the shaft must be faced so that it will ride on the centers evenly. A side tool is usually used to do the facing. See Fig. 11.



In facing with a side tool it may be necessary to face into the countersink hole. On reaching the edge of the countersink tail center may be withdrawn slightly. This enables the side tool to face the end clean.


When shaft is faced ready for general machining place a drop of oil on the tail stock center, also a drop in the counter-

sunk hole of shaft. Adjust the tail stock center so that the shaft has a slight play on the centers (it must not turn hard on the centers), then fasten the tail stock spindle by the binding clamp.

POSITION OF TOOL

The position of the turning tool is quite important in machining metal. In most work we find that a little above the center is the proper height. See Fig. 12.

Care should be taken that the tool does not extend too far from the tool post, especially on heavy cuts. The tool should be ground so that it will have plenty of clearance and make a sharp clean cut.



STANDARD SCREW THREADS

There are several different standards for the various screw threads, but general practice in the United States favors the Sharp V and the U. S. Standard. We show drawings of both herewith. Of the two Standards the U. S. is perhaps the most popular, but there are still a great many mechanics of the old school who prefer the Sharp V thread. In replacing a bolt or a screw it would be well to note whether it is the U. S. Standard or the Sharp V.

The American Licensed Automobile Manufacturers have adopted the Standard for screw threads which we show herewith.




FORMULA

$$P = \text{Pitch} = \frac{1}{\text{No. Threads Per Inch}}$$

$$D = \text{Depth} = P \times .64952$$

$$F = \text{Flat} = \frac{P}{8}$$

UNITED STATES STANDARD SCREW THREADS



$$\left\{ \begin{array}{l} P = \text{Pitch} = \frac{1}{\text{No. Threads Per Inch}} \\ D = \text{Depth} = P \times .6603 \end{array} \right.$$

SHARP V STANDARD SCREW THREADS

TABLE SHOWING PITCH OF THREAD and Sizes of Tap Drills for Standard Thread A. L. A. M. Standard Thread and Drill Sizes for Taps

Diam. Tap in. Ins.	Threads per inch	Size of Drill in. Ins.	Threads per inch	Size of Drill in. Ins.	Threads per inch	Size of Drill in. Ins.	Diam. in.	Pitch	Tap Drill
1/4	20	5/16 in.	18	11/16	16	3/4	1/4	28	No. 4
5/16	18	1/4 in.	16	13/16	14	7/8	5/16	24	17/64 in.
3/8	16	9/16 in.	14	15/16	12	1 1/8	3/8	24	21/64
7/16	14	5/8 in.	12	1 1/8	10	1 3/8	7/16	20	5/8
1/2	12	1 1/16 in.	10	1 3/8	8	1 7/8	1/2	20	7/16 in.
5/8	12	1 3/16 in.	10	1 5/8	8	2 1/8	5/8	18	1 1/8
3/4	11	1 1/2 in.	9	1 7/8	7	2 3/4	3/4	16	1 1/4
7/8	11	1 3/4 in.	8	2 1/4	6	3 1/4	7/8	14, 18	1 1/2
1	11	2 in.	7	2 3/4	5	3 3/4	1	14	1 3/4

THREAD CUTTING

In cutting screw threads on the lathe the carriage is always driven by clamping the half nuts on the lead screw, therefore, the friction feed should never be used when thread cutting. See that the feed knob is not tight, but loose or neutral so that neither the power cross feed nor the longitudinal feed can possibly get into action while cutting threads.

Pitch and lead do not always mean the same thing. The pitch of a thread is the distance from the center of one thread to the center of the next. The lead of a screw is the distance the nut will advance in one revolution of the screw. Where a screw is single thread the pitch and lead are the same. But when a screw has a double, triple, or multiple thread, the lead is as many times the pitch as there are multiple threads in the screw.

MEASURING SCREW THREADS




FIG. 70

The above illustration shows the method of finding the pitch of a screw when a thread gauge is not convenient.

Place a scale on the screw so that the end of the scale is opposite the first thread or any thread of the screw. In the drawing the dotted lines drawn down from the top of the first and ninth threads opposite the inch mark divides the first and the ninth threads in the middle, but on the lower side of the screw it divides them at the bottom of the thread. Counting the complete number of threads between these marks on the bottom of the screw you will find eight complete threads. There are, therefore, only eight threads per inch on this screw and the pitch is $\frac{1}{8}$ ".

In counting the threads on the top side where the scale is never include the last thread.

CHANGE GEARS FOR THREAD CUTTING

An index plate, as per illustration, is always attached to a lathe, showing the necessary gears to cut the desired thread. The headings of the three columns shown in plate are as follows:

Thread, means the number of threads to the inch that the operator wishes to cut.

Spindle, means the reverse spindle stud, which in this case revolves the same speed as the lathe spindle.

Screw, means lead screw, which drives the carriage of the lathe.

SOUTH BEND MACHINE TOOL CO. CHANGING GEAR INDEX		
THE SPINDLE SCREW		
2	24	32
3	32	40
4	40	48
5	48	56
6	56	64
7	64	72
8	72	80
9	80	88
10	88	96
11	96	104
12	104	112
13	112	120
14	120	128
15	128	136
16	136	144
17	144	152
18	152	160
19	160	168
20	168	176
21	176	184
22	184	192
23	192	200
24	200	208
25	208	216
26	216	224
27	224	232
28	232	240
29	240	248
30	248	256
31	256	264
32	264	272
33	272	280
34	280	288
35	288	296
36	296	304
37	304	312
38	312	320
39	320	328
40	328	336
41	336	344
42	344	352
43	352	360
44	360	368
45	368	376
46	376	384
47	384	392
48	392	400
49	400	408
50	408	416
51	416	424
52	424	432
53	432	440
54	440	448
55	448	456
56	456	464
57	464	472
58	472	480
59	480	488
60	488	496
61	496	504
62	504	512
63	512	520
64	520	528
65	528	536
66	536	544
67	544	552
68	552	560
69	560	568
70	568	576
71	576	584
72	584	592
73	592	600
74	600	608
75	608	616
76	616	624
77	624	632
78	632	640
79	640	648
80	648	656
81	656	664
82	664	672
83	672	680
84	680	688
85	688	696
86	696	704
87	704	712
88	712	720
89	720	728
90	728	736
91	736	744
92	744	752
93	752	760
94	760	768
95	768	776
96	776	784
97	784	792
98	792	800
99	800	808
100	808	816
101	816	824
102	824	832
103	832	840
104	840	848
105	848	856
106	856	864
107	864	872
108	872	880
109	880	888
110	888	896
111	896	904
112	904	912
113	912	920
114	920	928
115	928	936
116	936	944
117	944	952
118	952	960
119	960	968
120	968	976
121	976	984
122	984	992
123	992	1000
124	1000	1008
125	1008	1016
126	1016	1024
127	1024	1032
128	1032	1040
129	1040	1048
130	1048	1056
131	1056	1064
132	1064	1072
133	1072	1080
134	1080	1088
135	1088	1096
136	1096	1104
137	1104	1112
138	1112	1120
139	1120	1128
140	1128	1136
141	1136	1144
142	1144	1152
143	1152	1160
144	1160	1168
145	1168	1176
146	1176	1184
147	1184	1192
148	1192	1200
149	1200	1208
150	1208	1216
151	1216	1224
152	1224	1232
153	1232	1240
154	1240	1248
155	1248	1256
156	1256	1264
157	1264	1272
158	1272	1280
159	1280	1288
160	1288	1296
161	1296	1304
162	1304	1312
163	1312	1320
164	1320	1328
165	1328	1336
166	1336	1344
167	1344	1352
168	1352	1360
169	1360	1368
170	1368	1376
171	1376	1384
172	1384	1392
173	1392	1400
174	1400	1408
175	1408	1416
176	1416	1424
177	1424	1432
178	1432	1440
179	1440	1448
180	1448	1456
181	1456	1464
182	1464	1472
183	1472	1480
184	1480	1488
185	1488	1496
186	1496	1504
187	1504	1512
188	1512	1520
189	1520	1528
190	1528	1536
191	1536	1544
192	1544	1552
193	1552	1560
194	1560	1568
195	1568	1576
196	1576	1584
197	1584	1592
198	1592	1600
199	1600	1608
200	1608	1616
201	1616	1624
202	1624	1632
203	1632	1640
204	1640	1648
205	1648	1656
206	1656	1664
207	1664	1672
208	1672	1680
209	1680	1688
210	1688	1696
211	1696	1704
212	1704	1712
213	1712	1720
214	1720	1728
215	1728	1736
216	1736	1744
217	1744	1752
218	1752	1760
219	1760	1768
220	1768	1776
221	1776	1784
222	1784	1792
223	1792	1800
224	1800	1808
225	1808	1816
226	1816	1824
227	1824	1832
228	1832	1840
229	1840	1848
230	1848	1856
231	1856	1864
232	1864	1872
233	1872	1880
234	1880	1888
235	1888	1896
236	1896	1904
237	1904	1912
238	1912	1920
239	1920	1928
240	1928	1936
241	1936	1944
242	1944	1952
243	1952	1960
244	1960	1968
245	1968	1976
246	1976	1984
247	1984	1992
248	1992	2000
249	2000	2008
250	2008	2016
251	2016	2024
252	2024	2032
253	2032	2040
254	2040	2048
255	2048	2056
256	2056	2064
257	2064	2072
258	2072	2080
259	2080	2088
260	2088	2096
261	2096	2104
262	2104	2112
263	2112	2120
264	2120	2128
265	2128	2136
266	2136	2144
267	2144	2152
268	2152	2160
269	2160	2168
270	2168	2176
271	2176	2184
272	2184	2192
273	2192	2200
274	2200	2208
275	2208	2216
276	2216	2224
277	2224	2232
278	2232	2240
279	2240	2248
280	2248	2256
281	2256	2264
282	2264	2272
283	2272	2280
284	2280	2288
285	2288	2296
286	2296	2304
287	2304	2312
288	2312	2320
289	2320	2328
290	2328	2336
291	2336	2344
292	2344	2352
293	2352	2360
294	2360	2368
295	2368	2376
296	2376	2384
297	2384	2392
298	2392	2400
299	2400	2408
300	2408	2416
301	2416	2424
302	2424	2432
303	2432	2440
304	2440	2448
305	2448	2456
306	2456	2464
307	2464	2472
308	2472	2480
309	2480	2488
310	2488	2496
311	2496	2504
312	2504	2512
313	2512	2520
314	2520	2528
315	2528	2536
316	2536	2544
317	2544	2552
318	2552	2560
319	2560	2568
320	2568	2576
321	2576	2584
322	2584	2592
323	2592	2600
324	2600	2608
325	2608	2616
326	2616	2624
327	2624	2632
328	2632	2640
329	2640	2648
330	2648	2656
331	2656	2664
332	2664	2672
333	2672	2680
334	2680	2688
335	2688	2696
336	2696	2704
337	2704	2712
338	2712	2720
339	2720	2728
340	2728	2736
341	2736	2744
342	2744	2752
343	2752	2760
344	2760	2768
345	2768	2776
346	2776	2784
347	2784	2792
348	2792	2800
349	2800	2808
350	2808	2816
351	2816	2824
352	2824	2832
353	2832	2840
354	2840	2848
355	2848	2856
356	2856	2864
357	2864	2872
358	2872	2880
359	2880	2888
360	2888	2896
361	2896	2904
362	2904	2912
363	2912	2920
364	2920	2928
365	2928	2936
366	2936	2944
367	2944	2952
368	2952	2960
369	2960	2968
370	2968	2976
371	2976	2984
372	2984	2992
373	2992	3000
374	3000	3008
375	3008	3016
376	3016	3024
377	3024	3032
378	3032	3040
379	3040	3048
380	3048	3056
381	3056	3064
382	3064	3072
383	3072	3080
384	3080	3088
385	3088	3096
386	3096	3104
387	3104	3112
388	3112	3120
389	3120	3128
390	3128	3136
391	3136	3144
392	3144	3152
393	3152	3160
394	3160	3168
395	3168	3176
396	3176	3184
397	3184	3192
398	3192	3200
399	3200	3208
400	3208	3216
401	3216	3224
402	3224	3232
403	3232	3240
404	3240	3248
405	3248	3256
406	3256	3264
407	3264	3272
408	3272	3280
409	3280	3288
410	3288	3296
411	3296	3304
412	3304	3312
413	3312	3320
414	3320	3328
415	3328	3336
416	3336	3344
417	3344	3352
418	3352	3360
419	3360	3368
420	3368	3376
421	3376	3384
422	3384	3392
423	3392	3400
424	3400	3408
425		

COMPOUND GEARING

The compounding of gears for thread cutting is necessary when the pitch of the thread to be cut requires gears with a great number of teeth, and to avoid having large gears or a great number of small gears we resort to compounding.




Fig. 14

COMPOUND GEARS

Fig. 14 shows the arrangement of compound gears for cutting a 32 thread on a Lathe. The compound gears are 104 teeth and 52 teeth. It will be noted that these gears are two for one.

The index plate on the lathe, for the above compounding, calls for a 24-tooth gear on the spindle stud, and a 48-tooth gear on the lead screw. The Idler gear is necessary to connect the Compound gear with the screw gear. Any gear may be used as an Idler that will conveniently connect the two.




Fig. 15

Thread Cutting Stop

In cutting a thread it is necessary that a number of chips be taken. An adjustable stop for screw cutting, as illustrated in drawing above, is a very convenient arrangement for getting the depth of the chip. After bringing the tool up to the work, fasten the stop in position so that the head of the adjusting screw is close up to the stop. When ready to take the first cut turn this screw about $\frac{1}{4}$ of a turn. This limits the depth of the cut. Repeat this operation on each cut until the screw is finished.

SETTING OF THREAD TOOL

The cutting edge of thread tool should be ground to an angle of 60 degrees. The height of the tool should be set even with the lathe center. A thread or center gauge is used for the setting of the thread tool in order to give the proper angle on the thread. See Fig. 15.




Fig. 15




Fig. 16

Adjust the tool so that the edge of the thread gauge is parallel with the shaft or piece to be threaded. This thread gauge is also used as a templet for grinding the thread tool.

A similar method for setting the thread tool for cutting internal threads is shown in Fig. 16.

The thread tool being set and the change gears arranged to give the desired pitch, we are now ready for cutting the thread. If the material to be machined is mild steel plenty of oil should be used on the tool. The adjustable stop will regulate the depth of cut. The beginner should take very light chips. A little experience will teach him the proper depth.

THE FIRST CHIP

Before taking the first chip see that the dog on the shaft to be threaded is tight. See that there is oil on the tail center where it enters the shaft. See that your thread tool is fastened firmly in the tool post and that the automatic feed in the apron is not in action. See that the half nuts in apron are oiled thoroughly and that there is also oil on the lead screw.

Bring the point of the tool to the end of the shaft, clamp the half nuts firmly on the lead screw, and start the lathe. For the first cut let the tool enter only far enough to make a slight scratch as far as you wish the thread to extend. When you reach the end of the cut draw the tool out by turning the cross feed screw. Reverse the shipper rod. This reverses the direction of the lathe spindle and allows the carriage to travel back automatically. Usually two complete turns of the cross feed screw will withdraw the thread tool far enough to clear the thread, so that the tool will not destroy the thread on the return of the carriage. Continue this operation until thread is finished.

Piece being threaded should revolve slowly. On soft machine steel we would recommend a cutting speed of 25 feet per minute for the beginner. For example, cutting an 8-thread on $1\frac{1}{2}$ -inch soft steel shaft. The belt should be on the second slowest speed with back gear in.

When cutting threads on soft steel or iron use plenty of oil on the point of the cutting tool. If one has many threads to cut lard oil is recommended.

In cutting threads on cast iron, brass, aluminum, etc., oil is never used. The exception is, when threads are being cut by a die,

A lathe is even geared when the revolutions of the spindle and the revolutions of the spindle stud are the same.

On a lathe that is even geared, when cutting a screw having the number of its threads per inch exactly divisible by the number of threads per inch in the lead screw, it is not necessary to reverse.—the lathe may run in one direction all the time. When the tool has fed to the end of the cut draw it out as before, open the split nut, and reverse the carriage by hand. Throw in the split nut again, take another chip, and repeat this operation until the screw is finished. For example, if your lead screw is 8-thread and the screw that you wish to cut is divisible by eight, such as 8, 16, 24, 32, 40, etc., the above rule may be followed.

Never remove the driving dog from the screw that you are cutting until the thread is finished. Always put the tail of the dog into the same slot of face plate after testing the screw for size.

GRINDING TOOL AFTER THREAD HAS BEEN STARTED

After the thread has been started, if it is necessary to remove the tool for grinding before thread cutting is finished, take the tool out and grind it. After grinding adjust the thread tool as before, setting it opposite the thread groove. Turn the spindle forward by hand by pulling on the belt, and again test to see if the point of the tool is exactly opposite the thread in the work. If it is not opposite drop the reverse gear, turn the spindle forward by hand until the tool is exactly opposite the groove. Then connect the reverse gear as before. This throws in the feed, and you may proceed with the cutting.

In turning the spindle by hand ALWAYS TURN IT FORWARD. If you turn it backward there will be a back lash and it will not show the true position of the tool.

TURNING TAPER

To turn taper on a lathe, the tail stock is set off center a sufficient distance to give the desired taper.

Fig. 22 illustrates an automobile axle being tapered in a 16" South Bend Lathe.




FIG. 22

TURNING TAPER ON AN AUTOMOBILE AXLE

To set over tail stock for turning taper, loosen tail stock clamp, unscrew set screw F to the distance you think necessary, and screw in set screw G the same distance, or until it runs up against the tail stock hub. This will set over the top of the tail stock. Then clamp tail stock to bed and take a chip. Occasionally test the piece, being machined to see if the taper is correct.

In testing the taper of a piece that is being machined (a lathe center shank for example), take several chips off the blank, when the tapered end is small enough, insert it in the taper hole in which it is to fit. Carefully shake with thumb and finger. If there is a shake it will show whether the taper is too great or

not great enough. Adjust the tail stock to the lathe accordingly. Take a light chip, make another test. For a final test, make three chalk marks along the elements or side of the taper, place the tapered piece in the hole again and turn carefully by hand. If there is a high spot, it will show on the chalk mark. If it is a perfect fit, it will show along the entire length of the taper.

When extreme tapers are to be turned on a lathe, or where a number of similar parts are to be machined taper, such as in manufacturing, a taper attachment is recommended. We herewith show an illustration of the taper attachment used on South Bend Lathe. This attachment may also be used for boring taper holes, etc.




TAPER ATTACHMENT

The illustration shows a simple, but efficient taper attachment for lathe. This attachment is fitted to the rear V of the lathe by two clamps. These clamps may be adjusted along the entire length of the bed, so that the operator may turn taper in any position the whole length of the lathe.

DRILLING IN THE LATHE

Fig. 17 shows a lathe chuck mounted on the head spindle of the lathe and the drill chuck attached to the tail spindle. In this manner a great deal of drilling of duplicate pieces may be done quickly.



USING BOTH LATHE CHUCK AND DRILL CHUCK

In Fig. 5, page 22, the drill chuck is attached to the head spindle of lathe. Thus it may be seen that a chuck fitted to the tail spindle of the lathe, may be also used in the head spindle, as the taper in both spindles are the same. This feature will be found convenient for a great variety of work.


"How to Run a Lathe!" would make an excellent gift to a friend who is interested in mechanics. We will mail a copy postpaid direct to his address upon receipt of price. Stamps accepted.



USING THE LATHE AS A DRILL PRESS

The illustration shows a drilling job being done on the lathe. The drill is 1-inch diameter, the piece to be drilled is steel 1-inch thick. The cutting feed is operated by the hand wheel of tail stock. Drilling of almost any nature can be done in a lathe to advantage. The size of hole may range all the way from 1-16" to 1 1/2" in diameter.

In the drilling operation above the back gears are in mesh on the lathe, so that the power delivered at the point of the drill is equal to the power of a 24" back geared drill press. Practically any drilling job that can be done on the drill press may also be done on the lathe, because the lathe is a universal machine for the general machine shop.



A SHAFT IN THE CENTER REST

Fig. 18 shows a shaft supported by the center rest and being driven by the lathe chuck. This shaft is 3" in diameter and 12' long. A $\frac{3}{4}$ " hole is to be drilled its entire length, so it is necessary to center the shaft so that the drill will start true. Cut shows the centering tool held in the tool post. The point of this tool is ground exactly like the point of an ordinary flat drill. To center the shaft, start the lathe, adjust the tool in so that it is approximately at the center of the shaft. Move the tool rest, so that when the tool begins cutting it will show the exact center, and will machine a countersunk hole.

When this countersunk hole is about $\frac{1}{8}$ " deep remove the centering tool, attach your drill to tail spindle, as shown in Fig. 17, and proceed with the drilling, using the hand-wheel of tail stock for feeding.

MILLING AND KEY-WAY CUTTING ATTACHMENT FOR LATHES



Milling in the Lathe

The illustration above shows a milling and key-way cutting attachment fitted to a South Bend Lathe. A piece of cast iron is held in the vise and an angle milling cutter, which also acts as a face mill, is fitted to the spindle of the lathe. The length of the cut is controlled by the cross feed screw, the depth by the adjustment of lathe carriage, and the vertical adjustment governed by the vertical screw.

The attachment is fitted on the top of the Compound Rest base, located by a center pin projecting from base. The fixture is fastened to the Compound Rest base with two bolts, in the same manner as the Compound Rest top is fastened. This attachment can be used only on a lathe fitted with a Compound Rest.

A milling attachment for a lathe is practical in the shop because it equips the lathe for doing a great deal of work that could be done only on a shaper or a milling machine. An attachment of this kind can take care of a variety of jobs, as it swivels all the way around on a horizontal plane and is graduated in degrees. It swivels 180 degrees on a vertical plane and is graduated. The vertical adjusting screw has a graduated collar reading in one-thousandth of an inch.

KEYSEATING A STEEL SHAFT

Fig. B shows No. 3 attachment cutting a key-way $\frac{1}{2}$ -inch wide and 3-16-inch deep in a 2-inch steel shaft. The work is being done on a 13-inch lathe.




Fig. B




Fig. D
Key Seating Woodruff System

In Fig. D the illustration is taken from the back of lathe, and shows the attachment holding an inch and a half steel shaft which has been key-seated for the Woodruff system of key. A special chuck is fitted to the spindle lathe for holding the cutter.



Fig. C

Squaring a Steel Shaft

The four illustrations above show the milling attachment doing four different jobs. This is the same size attachment in each case.

Fig. C shows a No. 3 milling attachment fitted to a 13-inch lathe squaring an inch and a half steel shaft. The shaft is held by V blocks in the vise. The same method may be used for sawing off shafting or tubing by using a saw on the arbor.

The shaft in cut may also be squared by turning the attachment at right angles. That is, to let the shaft approach the cutter from the end.

The four illustrations above show the milling attachment doing four different jobs.

SOUTH BEND SPECIAL MILLING ATTACHMENT

The illustration shows our special milling attachment for lathe-equipped with a milling machine vise. This attachment is used only for special work.



Fig. E

SIDE MILLING CUTTERS FOR MILLING AND KEYWAY CUTTING ATTACHMENT

These cutters have teeth upon both sides and face and may be used for a variety of jobs. For example in cutting a keyway a half-inch wide, a quarter-inch cutter may be used by taking two chips for the width of the keyway, or a half-inch cutter may be used taking full width of cut in one chip. See cut Fig. B.



Fig. F

No.	Diameter	Width of Face	Hole
16	2 1/2	1 1/4	7/8
17	2 1/2	1 1/8	7/8
18	2 1/2	1 1/8	7/8
19	2 1/2	1 1/8	7/8
20	2 1/2	1 1/8	7/8
21	2 1/2	1 1/8	7/8
22	2 1/2	1 1/8	7/8
23	2 1/2	1 1/8	7/8
24	2 1/2	1 1/8	7/8
25	2 1/2	1 1/8	7/8
26	3	1 1/2	1
27	3	1 1/2	1
28	3	1 1/2	1
29	3	1 1/2	1
30	3	1 1/2	1

MILLING ARBOR FOR LATHE



Fig. G

The illustration shows arbor to be used with the South Bend milling and keyway cutting attachment. This arbor fits into the head spindle of lathe. For holding cutters see cut Fig. B.

The arbor is made in three sizes, 3/4", 7/8", and 1" diameter. The 1-inch arbor is the most practical.

FORGED STEEL LATHE TOOLS

The twelve lathe tools below have been selected as the most practical set of forged tools for general all-round work on the lathe. These tools are made both in carbon and the high speed steels. The size of the tools vary to suit the different size lathes.




- 1 Left-hand Side Tool.
- 2 Right-hand Side Tool.
- 3 Right-hand Bent Tool.
- 4 Right-hand Diamond Point.
- 5 Left-hand Diamond Point.
- 6 Round Nose Tool.
- 7 Cutting-off Tool.
- 8 Threading Tool.
- 9 Bent Threading Tool.
- 10 Roughing Tool.
- 11 Boring Tool.
- 12 Inside Threading Tool.

KNURLING IN THE LATHE

The cut herewith shows a piece of steel with three different grades of knurling. The knurling tool for doing this work is also shown. This tool is held in the tool post of lathe; piece to be knurled is driven slowly on centers or in a chuck; tool is forced slowly into the work as it revolves, and this in turn revolves the knurl wheels, thus the impression is produced. The knurl wheels are hardened. Plenty of oil is used during the operation.


SAMPLE OF KNURLING



Coarse Medium Fine

Knurling Tool





**No. 35 — 13-INCH TOOL ROOM LATHE WITH
GEAR GUARDS AND OIL PAN**

The lathe illustrated above is equipped with gear guards which completely cover all exposed gears. There is a hinged gear guard on the end that covers the reverse and change gears. When the operator wishes to change a gear all that is necessary is to swing back the hinge guard, make the necessary gear changes, and bring the guard back into position.

The oil pan shown in cut is principally used in tool room work and light manufacturing. Sometimes an oil pump is used on a lathe of this kind pouring a constant stream of oil on the work. This pan collects both the oil and chips.

It will be noted that the lathe bed is equipped with two short bench legs which set upon the pan. This No. 35 lathe is often used as a bench lathe, the oil pan and long legs being omitted.



**COUNTERSHAFT AND REGULAR EQUIPMENT
WITH 15-INCH LATHE**


All Included in the Price of Lathe

The equipment illustrated above is for a 16" Lathe and includes, as shown:

- | | |
|-------------------------------|-------------------------------|
| One Small Face Plate. | One Set of Change Gears for |
| One Large Face Plate. | Screw Cutting. |
| One Center Rest. | Necessary Wrenches for Lathe. |
| Two Steel Centers. | One Double Friction Counter- |
| One Follower Rest. | shaft Complete. |
| One Adjustable Stop for Screw | |
| Cutting. | |

The countershaft is one of the very important attachments of a lathe because it is always on duty when the lathe is in operation and attached to the ceiling it is not easily accessible.

The countershaft is simple, practical, and efficient, and will give excellent results year after year. The only attention it needs is about five minutes a week for oiling.



16-INCH LATHE BORING A 30-INCH FLY WHEEL

Gap Bed Lathe equipped with Raising Blocks

The practical application of the gap bed and raising blocks to the lathe may be seen in the above case where the operator was able to do a job on a 16-inch lathe that otherwise would require a 30-inch lathe.

The gap bed lathe with bridge is a very practical tool for the general machine and repair shop that is called upon to do a great variety of work. If a job of large diameter comes in it is a simple matter to remove the bridge, machine the job, replace the bridge, so the lathe may be used as regular straight bed lathe for ordinary work.

HOW TO TEMPER A LATHE TOOL

A lathe tool is made of crucible or tool steel. Care should be used in heating the tool while forging. It should be heated slowly and evenly. After the tool is forged then file or grind into shape. To harden and temper the tool heat slowly for a distance of about $1\frac{1}{2}$ inches from cutting point. When it comes to a cherry red, immerse the tool in cold water about one inch. This leaves some heat in the shank which will assist in drawing the temper. After the point has become cool, remove the tool, polish the hardened surface with a piece of emery cloth, then wipe this polished surface with an oily rag. The heat in the shank of the tool will now drive the temper toward the cutting edge. When this edge becomes a brown straw color immerse the entire tool in cold water.


After the tool is hardened and tempered, grind on a fine wheel, being careful not to get the tool heated so as to draw the temper.

When you want a cutting tool exceptionally accurate and durable, such as for thread cutting, rub the cutting edge by hand with a small oil stone. This will increase the efficiency and the wearing qualities.

HOW TO ANNEAL A PIECE OF TOOL STEEL

Heat the steel slowly and evenly to a dark red. Then place in box of lime or ashes, cover completely and let remain over night. In the morning the piece will be annealed ready for machining.

To water-anneal a piece of tool steel, heat slowly and evenly until a dark red. Then hold in the tongs in a shaded corner until all color has left. Place a small pine stick against the steel. When the steel is cool enough so that it will not smoke the pine stick then immerse the steel quickly into cold water and it is ready for machining.



RAISING BLOCKS

A 15-inch Lathe Blocked to Swing 20 inches

The above cut illustrates a 15-inch lathe equipped with raising blocks to swing 20 inches over the bed. The raising block equipment includes blocks for head stock, tail stock, tool rest, center rest, also the necessary bolts and screws for attaching blocks to lathe.

The advantage of raising blocks for a lathe for the general all-round shop is appreciated when one has a job of large diameter to be machined. He can attach his blocks, practically making a 20-inch lathe out of a 15-inch lathe at a very slight cost. When the job of large diameter is finished simply remove the blocks and save them until the next large job comes along.

WOODRUFF SYSTEM KEYSEAT




The drawing herewith shows a shaft that has been milled for a Woodruff key, with key inserted. "A" equals the thickness of key. The key should project above the shaft one-half its thickness.

STANDARD KEY-WAYS FOR PULLEYS AND SHAFTS

This diagram shows the recognized standard for the depth and width of key-way in pulleys. The same formula of course may be used for the depth and width of key-way in shaft.

Here we give a list of the standard sizes both for pulleys and shaft.



Diameter (D) of Hole	Width (W) of Keyway	Depth (H) of Keyway	Radius (R)
3-8" to 3-16"	3-32"	5-64"	
3-8" to 7-8"	1-8"	1-16"	.020
13-16 to 1-1-8"	5-32"	5-64"	.025
1-1-16 to 1-3-8"	3-16"	3-32"	.040
1-7-16 to 1-5-8"	1-4"	1-8"	.050
1-13-16 to 2"	5-16"	5-32"	.060
2-1-16 to 2-1-2"	3-8"	3-16"	.060
2-7-16 to 2"	7-16"	2-16"	.060

THE SIZING AND CUTTING OF GEAR WHEELS

Diameter, when applied to gears, is always understood to mean the pitch diameter.

Diametral Pitch is the number of teeth to each inch of the pitch diameter.

Example. If a gear has 40 teeth and the pitch diameter is 4 inches, there are 10 teeth to each inch of the pitch diameter and the diametral pitch is 10, or in other words, the gear is 10 diametral pitch.

Diametral Pitch required, circular pitch given. Divide 3.1416 by the circular pitch.

Example. If the circular pitch is 2 inches, divide 3.1416 by 2 and the quotient, 1.5708, is the diametral pitch.

Diametral Pitch required, number of teeth and outside diameter given. Add 2 to the number of teeth and divide by the outside diameter.

Example. If the number of teeth is 40, the diameter of the blank is $10\frac{1}{2}$ inches; add 2 to the number of teeth, making 42, and divide by $10\frac{1}{2}$; the quotient, 4, is the diametral pitch.

Circular Pitch is the distance from the center of one tooth to the center of the next, measured along the pitch line.

Example. If the distance from the center of one tooth to the center of the next tooth, measured along the pitch circle, is $\frac{1}{2}$ inch, the gear is $\frac{1}{2}$ inch circular pitch.

Circular Pitch required, diametral pitch given. Divide 3.1416 by the diametral pitch.

Example. If the diametral pitch is 4, divide 3.1416 by 4 and the quotient, .7854 inch, is the circular pitch.

Number of Teeth required, pitch diameter and diametral pitch given. Multiply the pitch diameter by the diametral pitch.

Example. If the diameter of the pitch circle is 10 inches and the diametral pitch is 4, multiply 10 by 4 and the product, 40, will be the number of teeth in the gear.

Number of Teeth required, outside diameter and diametral pitch given. Multiply the outside diameter by the diametral pitch and subtract 2.

Example. If the whole diameter is $10\frac{1}{2}$ and the diametral pitch is 4, multiply $10\frac{1}{2}$ by 4 and the product, 42, less 2, or 40, is the number of teeth.

Pitch Diameter required, number of teeth and diametral pitch given. Divide the number of teeth by the diametral pitch.

Example. If the number of teeth is 40 and the diametral pitch is 4, divide 40 by 4 and the quotient, 10, is the pitch diameter.

Outside Diameter or size of gear blank required, number of teeth and diametral pitch given. Add 2 to the number of teeth and divide by the diametral pitch.

Example. If the number of teeth is 40 and the diametral pitch is 4, add 2 to the 40, making 42, and divide by 4; the quotient, $10\frac{1}{2}$, is the whole diameter of the gear or blank.

Thickness of Tooth at Pitch Line required. Divide the circular pitch by 2, or 1.57 by the diametral pitch.

Example. If the circular pitch is 1.047 inch, or the diametral pitch is 3, divide 1.047 by 2, or 1.57 by 3, and the quotient, .523 inch, is the thickness of tooth.

Whole Depth of Tooth required. Divide 2.157 by the diametral pitch.

Example. If the diametral pitch of a gear is 6, the whole depth is 2.157 divided by 6, which equals .3595.

Whole Depth of Tooth is about 11-16 or exactly .6866 of the circular pitch.

Example. If the circular pitch is 2, the whole depth of tooth is about 11-16 of 2 inches or $1\frac{3}{8}$ inches nearly.

Distance Between Centers of two gears required. Add the number of teeth together and divide one-half the sum by the diametral pitch.

Example. If the two gears have 50 and 30 teeth, respectively, and are 5 pitch, add 50 and 30, making 80, divide by 2, and then divide the quotient, 40, by the diametral pitch, 5, and the result, 8 inches, is the center distance.

INDEPENDENT LATHE CHUCK

With Four Independent Reversible Jaws



Independent Lathe Chucks

The chuck illustrated above is a 12" independent lathe chuck. The jaws are operated independently of each other and are reversible.


The independent chuck is used for holding heavy pieces and pieces of irregular shape, and is the most practical chuck for the lathe on general work.

UNIVERSAL GEARED SCROLL CHUCK

With Two Sets of Jaws

Illustration shows a 6", 3 jaw universal geared scroll chuck with two sets of jaws. The number 1 jaws are shown in the chuck, and the number 2 jaws are shown along side.

This style chuck is used for holding round pieces. The jaws are moved simultaneously by a scroll threaded disc which is operated by a wrench.



Universal Geared Scroll Chuck

COMBINATION CHUCK, GEARED SCREW

With Patent Reversible Jaws



A Combination Chuck is a combination of a Universal and an Independent Chuck. The jaws work universally to and from the center, but by shifting a stud on the back of chuck, throwing gears out of mesh, the jaws work independently.

Rear View of Lathe Chuck

Fig. 30 shows the rear view of a lathe chuck. It will be noted that there is a recess machined in the back of the chuck. This recess allows the chuck plate to be fitted for attaching chuck to lathe.



Fig. 30



Fig. 31

A SEMI-MACHINED CHUCK PLATE

Fig. 31 shows a Cast Iron Semi-Machined Chuck Plate. It is called "semi-machined" because it has been bored, faced, and threaded to fit the spindle nose of the lathe it is intended for.

To fit a lathe chuck to the spindle, select a semi-machined chuck plate with the flange large enough so that it may be turned to fit the recess in the chuck it is intended for. Screw this chuck plate on the spindle nose so that the hub of the plate fits up against the shoulder of spindle. Machine the chuck plate all over and turn the diameter of the flange to fit the recess of chuck, as shown in Fig. 30. The fit should be accurate,—not tight nor loose, but just right. Remove the chuck plate from the spindle, drill the necessary holes in plate, 1-16" larger than screw, attach it to the chuck with proper screws. Chuck is fitted ready for use.

When ordering a lathe and you wish a chuck included, always specify that the chuck be fitted to the lathe complete with chuck plate before the lathe leaves factory. The lathe manufacturer has suitable equipment for machining and fitting lathe chucks to lathes of their own make, charging approximately the actual cost of the labor and material; their object being that when the lathe and chuck reaches the customer it will fit accurately and give no trouble whatever.


SIZE OF LATHE CHUCKS FOR A LATHE

We show herewith a list giving the size of lathe chuck most suitable for the various size lathes. Of course it may be necessary to depart from this list for special work but for general all-around work in the Machine shop these sizes will be found practical.

11-inch Lathe.....	4" to 6"	inclusive
12-inch Lathe.....	4" to 8"	inclusive
13-inch Lathe.....	5" to 9"	inclusive
15-inch Lathe.....	6" to 10"	inclusive
16-inch Lathe.....	6" to 12"	inclusive
18-inch Lathe.....	8" to 14"	inclusive


METRIC THREADS ON AN ENGLISH LEAD SCREW

To cut Metric Threads on a South Bend Lathe using a regular standard English lead screw, use the Compound Idler or connecting gears 50 and 127, the No. 127 Gear to mesh with spindle stud. Use an idler to connect the 50-tooth Gear with Gear on Lead Screw.



Arrangement of Gearing to Cut 16 Thread per Centimeter on a No. 34 South Bend Lathe.

When Metric Threads are to be cut as above the regular Index Chart of lathe may be used in selecting gears for the different pitches. Read the chart as so many threads per centimeter, instead of so many threads per inch.




Grinding a Blanking Die on Lathe.

GRINDING ATTACHMENT FOR LATHE

The above illustration shows the practical application of a grinding attachment fitted to the lathe. The operation shows a round blanking die being ground for clearance. The grinding attachment is held in the tool post, the emery wheel being driven by an overhead drum that is usually about 10 to 14 inches in diameter. This drum is in turn driven from the lathe counter-shaft. The length of the drum depends upon the work to be ground. For example, when grinding a printer's roll that is 4-feet long on the lathe the overhead drum should at least be 6-feet 4-inches in length.

A great many different jobs may be ground on a lathe to good advantage. It is a very simple matter for the operator to build his own attachment, for he can then meet the exact conditions required for his work.



Regular equipment, as illustrated under lathe, is included in price.

No. 29 — 11-INCH SOUTH BEND LATHE

Fitted with Automatic Longitudinal and Power Cross Feeds

The No. 29 11" South Bend Lathe is used extensively in the laboratory, the tool room and the manufacturing plant, where light accurate work is required.

This Lathe may be furnished with bench legs if desired. A great many of these small Lathes are used on a bench instead of being equipped with long legs.

A practical tool equipment for this Lathe is as follows:

- 6" 4-Jaw Independent Lathe Chuck.
- $\frac{3}{8}$ " Drill Chuck.
- Set of 12 Forged Steel Lathe Tools.
- Set of 4 Lathe Dogs from $\frac{3}{8}$ " to 1" inclusive.

THE CUTTING SPEED FOR DIFFERENT METALS

The following cutting speed is recommended where high speed cutting tools are used:

Cast Iron	55 feet per minute
Machine Steel	35 " " "
Wrought Iron	40 " " "
Tool Steel, Annealed.....	25 " " "
Brass	100 " " "
Bronze	70 " " "
Grey or Red Fiber.....	50 " " "

HOW TO CALCULATE CHANGE GEARS FOR THREAD CUTTING ON AN ENGINE LATHE

The following rule shows how to calculate gearing to cut any thread on a Screw Cutting Engine Lathe, viz:

Multiply both the number of threads in the lead screw and the number of threads in the bolt to be cut, by any number. This will give you the number of teeth in the gears that can be used in cutting the thread. For example:

Threads to be cut, 12 per inch. Lead Screw on Lathe 6 threads per inch. Multiply both by any number, say 4:

$$12 \times 4 = 48 \quad 6 \times 4 = 24$$


48 and 24 are the gears to use.

If you have not the 48 and 24 gears, try multiplying by 5:

$$12 \times 5 = 60 \quad 6 \times 5 = 30$$

If the Thread to be cut is finer than the Thread in the Lead Screw, the smaller gear goes on spindle—while the larger gear goes on the Lead Screw.

Always measure the thread when you have taken the first chip to be sure that you have made no mistake.



Regular equipment as illustrated under Lathe is included in the price.


No. 34 — 13-INCH SWING SOUTH BEND SCREW LATHE Fitted with Automatic Longitudinal Feed and Power Cross Feed

The No. 34 Lathe illustrated above is surpassed by none for general all-around work in the Machine Shop and general repair shop. It has a great many practical features that makes it valuable in manufacturing and which enables it to take care of the various jobs that come up.

A practical equipment for the above lathe for general machine shop use is as follows:

- 9" 4-Jaw Independent Lathe Chuck.
- $\frac{1}{2}$ " Drill Chuck.
- Set of (12) Forged Steel Lathe Tools.
- Set of (6) Lathe Dogs $\frac{1}{2}$ " to $1\frac{1}{2}$ " inclusive.

For details write for South Bend Lathe Catalog.



Regular equipment, as illustrated under lathe, is included in price

No. 37 — 15 INCH SOUTH BEND LATHE

Fitted with Automatic Longitudinal and Power Cross Feeds

The No. 37 Lathe illustrated above is a practical tool for manufacturing, for the Machine Shop and general repair shop. It is intermediate in size and weight between the 13" and 16" Lathes. This 15" Lathe in an 8' bed is capable of taking care of a great variety of work.

A practical equipment for the above lathe for general shop use is as follows:


- 10" 4-Jaw Independent Lathe Chuck.
- $\frac{3}{4}$ " Drill Chuck.
- Set of (12) Forged Steel Lathe Tools.
- Set of (12) Lathe Dogs $\frac{1}{2}$ " to 4" inclusive.

For details write for South Bend Lathe Catalog.

DON'TS FOR MACHINISTS

From "Machinery"

- Don't run a Lathe with the belt too loose.
- Don't run the point of your lathe tool into the mandrel.
- Don't rap the chips out of your file on the lathe shears.
- Don't set a lathe tool below the center for external work.
- Don't start up a lathe without seeing that the tailstock spindle is locked.
- Don't put an arbor or shaft on lathe centers without lubricant on them.
- Don't leave too much stock on a piece of work to take off with the finishing cut.
- Don't try a steel gage or an expensive caliper on a shaft while it is running.
- Don't put a mandrel into a newly bored hole without a lubricant of some kind on it.
- Don't put a piece of work on centers unless you know that the internal centers are clean.
- Don't try to straighten a shaft on lathe centers, and expect that the centers will run true afterwards.
- Don't put a piece of work on lathe centers unless you know that all your centers are at the same angles.
- Don't set the cutting point of a lathe or planer tool any farther out from the toolrest than is absolutely necessary.
- Don't take a lathe center out of its socket without having a witness mark on it, and put it back again according to the mark.
- Don't start polishing a shaft on lathe centers without having it loose enough to allow for the expansion by heat from the polishing process.
- Don't run your lathe tool into the faceplate.
- Don't try to knurl a piece of work without oiling it.
- Don't run a lathe an instant after the center begins to squeal.
- Don't forget to oil your machine every morning; it works better.



Regular equipment, as illustrated under lathe, is included in price

No. 40 — 16-INCH SOUTH BEND LATHE

Fitted with Automatic Longitudinal and Power Cross Feeds

The No. 40 Lathe is used in general manufacturing, also in the Machine Shop and the practical all-around repair shop where the work is heavy, requiring a lathe of considerable stiffness and strength. This 16" Lathe in 8 or 10' bed will give excellent results for general work because it is capable of taking care of practically any job that comes up.

A practical equipment for the above lathe for general shop use is as follows:

- 12" 4-Jaw Independent Lathe Chuck.
- 1" Drill Chuck.
- Set of (12) forged steel lathe tools.
- Set of (12) Lathe Dogs $\frac{1}{2}$ " to 4" inclusive.

For details write for South Bend Lathe Catalog.

DON'TS FOR MACHINISTS

From "Machinery"

- Don't forget that a fairly good center-punch may be made from a piece of round file.
- Don't forget that a surface, polished with oil will keep clean much longer than one polished dry.
- Don't forget that the closer you can get your toolrest to the work, the better it is.
- Don't start to turn up a job on lathe centers unless you know that the centers are both in line with the ways.
- Don't cross your belt laces on the side next to the pulley, for that makes them cut themselves in two.
- Don't try to cut threads on steel or wrought iron dry; use lard oil or a cutting compound.
- Don't run a chuck or faceplate up to the shoulder suddenly; it strains the spindle and threads and makes removal difficult.
- Don't screw a tool post screw any tighter than is absolutely necessary; many mechanics have a false idea as to how tight a lathe tool should be to do its work.
- Don't leave a wrench in a chuck; always remove it.

When using the automatic cross or longitudinal feed on a lathe be sure that the **split nut is not closed** on the lead screw.

To drive the center out of head spindle use a rod and drive through the hole in spindle.

When putting a lathe chuck on the head spindle, always remove the center, because many times in drilling a piece on the chuck the operator forgets that the center is in and drills right through the job destroying the center.

When the center is removed from the head spindle of the lathe, always put a piece of rag in spindle hole to prevent any dirt from collecting.

INDEX

Annealing Tool Steel.....	47	Lathe, 16-inch Swing.....	42
Apron, Automatic Feed.....	7	Lathe Accessories.....	20
Arbor for Milling.....	42	Lathe Centers.....	19
Bellings for Lathe.....	14	Lathe Chucks.....	32
Carriage for Lathe.....	18	Lathe Countershaft.....	45
Centers for Lathe.....	19	Lathe as a Drill Press.....	27
Cutting.....	31	Lathe, Size of.....	12
Change Gears for Thread Cutting.....	29	Lathe Tools.....	43
Chucks, Lathe.....	25	Lathe, Gap Bed.....	44
Chucks for Lathe, Size of.....	55	Lathe with Raising Blocks.....	43
Chuck Plate, Semi-Machined.....	54	Layout for Small Shop.....	3
Combination Lathe Chucks.....	53	Measuring the Pitch of a Screw.....	38
Compound Gearing for Thread.....	30	Rule.....	38
Cutting.....	30	Metric Threads.....	55
Compound Rest, Graduated.....	9	Milling Cutters.....	42
Countershaft for Lathe.....	45	Milling and Keyway Cutting.....	39
Countershaft, Speed of.....	15	Attachment.....	39
Countersinking.....	62	Oil Pan for Lathe.....	44
Cutters for Milling.....	42	Practical Layout for Small Shop.....	3
Cutting Thread on any Lathe.....	58	Position of Cutting Tool.....	24
Rule.....	58	Raising Blocks for Lathe.....	43
Cutting Speed for Metal.....	53	Repair Parts.....	3
Don'ts on Lathe.....	61-63	Reverse.....	3
Drill and Countersink.....	22	Rule for Cutting Threads.....	39
Drilling in a Lathe.....	36	Screw Threads, Standard.....	27
Drill Press Operation.....	27	Semi-Machined Chuck Plate.....	54
Equipment of Lathe.....	45	Setting Thread Tool.....	31
Face Plates.....	18	Simple Gearing for Thread Cutting.....	29
Facing End of Shaft.....	25	Size of Chuck for Lathe.....	35
Forged Steel Lathe Tools.....	43	Speed and Sizes of Pulleys, Rule.....	15
Figuring Change Gears, Rule.....	53	Speed of Lathe Countershaft.....	15
Gap Bed Lathe.....	46	Speed of Line Shaft.....	2
Gear Guards for Lathe.....	44	Speed for Cutting Metal.....	58
Gear Scroll Chuck.....	52	Taper Attachment.....	35
Gears, Figuring Sizes, Rule.....	50	Taper Turning on Automobile.....	34
Grinding Attachment for Lathe.....	54	Axle.....	34
Grinding Thread Tool.....	33	Tempering Lathe Tools.....	47
Hardening a Lathe Tool.....	6	Thread Cutting.....	38
Horse Power to Drive Lathe.....	52	Thread Cutting Stop.....	50
Independent Lathe Chuck.....	39	Threads, Metric.....	55
Keyway Cutting Attachment.....	49	Tool Room Lathe.....	44
Keyways for Shafts and Pulleys.....	43	Turning Taper.....	34
Lathe, 11-inch Swing.....	57	Universal Chuck.....	32
Lathe, 13-inch Swing.....	59	Woodruff System Key Seat.....	49
Lathe, 15-inch Swing.....	60	Woodruff System Keyway Cutting.....	39

A FEW USERS OF SOUTH BEND LATHES

INTERNATIONAL HARVESTER CO., Yer Co., Detroit, Mich.	GENERAL ELECTRIC CO., Schenectady, N. Y.	U. S. GOVERNMENT, Washington, D. C.
COLORADO FUEL & IRON CO., Pueblo, Colo.	SINGER SEWING MACHINE CO., New York	U. S. GOVERNMENT, Pensacola, Fla.
ITALY REDUCTION CO., LTD., Hedley, B. C., Canada	AURORA AUTO. & CHINERY CO., Chicago, Ill.	U. S. GOVERNMENT, Fort Sill, Okla.
MINNESOTA FOUNDRY & MACHINE CO., Jackson, Minn.	DOMINION TEXTILE CO., Ltd., Montreal, Que.	HARRIS KNITTING MILLS, Pittsburgh, Pa.
JOHN HILLEN & SONS, Toronto, Ont.	UNITED KANSAS PORTLAND CEMENT CO., Topeka, Kan.	U. S. GOVERNMENT, Monroeville, N. H.
CASE BROS. CUTLERY CO., Springville, N. Y.	THE STATE TRADING CO., Bridgeport, Conn.	ROSLINE LUMBER CO., Bellevue, Ark.
J. & P. COATES CO., INC., Pawtucket, R. I.	NEW ENGLAND ENGINEERING CO., Watertown, Conn.	DAVID BRADLEY MFG. CO., Bradley, Ill.
GARDEN CITY FEEDER CO., Palo Alto, Iowa	HARVARD UNIVERSITY, Cambridge, Mass.	CENTRAL TEXAS ICE CO., Mexia, Texas
NOVA SCOTIA STEEL & COAL CO., Sydney Mines, N. S.	WESTERN STATE NORMAL SCHOOL, Kalama, Wash.	STANDARD STEELWORKS CO., New York
CHESAPEAKE & OHIO RAILWAY CO., Hinton, W. Va.	STANDARD SANITARY MFG. CO., New Britain, Pa.	UNION PACIFIC RAILROAD Omaha, Neb.
THOMAS A. EDISON, Orange, N. J.		

Thousands of South Bend Lathes are in service in manufacturing plants, machine shops, repair shops, textile mills, mines, mills, and automobile shops.